

crypto_aead
aes128n8t8c10cv2
implementations
amd64 Bobcat
amd64 K8
amd64 K10 65nm
amd64 K10 45nm
amd64 K10 32nm
amd64 Bulldozer
amd64 Piledriver
amd64 Zen
amd64 Zen 2
amd64 Zen 3
amd64 Knights Landing
amd64 Golden Cove
amd64 Cascade Lake
amd64 Tiger Lake
amd64 Skylake+512x2
amd64 Ice Lake
amd64 Comet Lake
amd64 Cannon Lake
amd64 Coffee Lake
amd64 Kaby Lake
amd64 Skylake
amd64 Broadwell+AES
amd64 Haswell+AES
amd64 Ivy Bridge+AES
amd64 Sandy Bridge+AES
amd64 Sandy Bridge
amd64 Westmere
amd64 Core 2 45nm
amd64 Core 2 65nm
amd64 Gracemont
amd64 Tremont
amd64 Goldmont Plus
amd64 Goldmont
amd64 Airmont
amd64 Silvermont
amd64 Bonnell
ppc32 G3
riscv64 U54
mips32 Oction II
armeabi Armada
armeabi Cortex-A7
armeabi Cortex-A8
armeabi Cortex-A9+NEON
armeabi Cortex-A15
aarch64 X-Gen
aarch64 Cortex-A53
aarch64 Cortex-A53+crypto
aarch64 Cortex-A57+crypto
aarch64 Cortex-A72
aarch64 Cortex-A72+crypto
aarch64 ThunderX2

T:aesni

?:aesni

T:ref

?:ref

bBobcat: 2 x 1650MHz; 2011 AMD G-T56N; amd64; Bobcat (600F10); supercop-20230630
b4650: 2 x 1650MHz; 2011 AMD E-450; amd64; Bobcat (600F20); supercop-20230618
baca: 2 x 2000MHz; 2006 AMD Athlon 64 X2; amd64; K8 (40f2b); supercop-201710105
gcc16: 8 x 2194MHz; 2008 AMD Opteron 8354; amd64; K10 65nm (100F23); supercop-20171218
hydra3: 6 x 3300MHz; 2010 AMD Phenom II X6 1100T; amd64; K10 45nm (100F40); supercop-20171218
sonnigstar: 4 x 3200MHz; 2009 AMD Phenom II X4 955; amd64; K10 45nm (100F42); supercop-20170904
b3aw: 1 x 1700MHz; 2010 AMD Athlon II Neo K125; amd64; K10 45nm (100F63); supercop-201710105
hydra4: 4 x 2900MHz; 2011 AMD A6-3850; amd64; K10 32nm (300F10); supercop-20230630
hydra5: 4 x 2900MHz; 2011 AMD A6-3850; amd64; K10 32nm (300F10); supercop-20230630
hydra9: 2 x 3800MHz; 2012 AMD A10-5800K; amd64; Piledriver (610F01); supercop-20171218
hptriaty: 2 x 2000MHz; 2012 AMD A10-6650M; amd64; Piledriver (610F01); supercop-20230618
z56as: 8 x 3300MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
z56ab: 8 x 3300MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
z56aa: 4 x 3300MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
z56ab: 4 x 3300MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
dall: 2 x 1800MHz; 2020 AMD Ryzen 9 5900X; amd64; Zen 3 (600H11); supercop-20221222
r500: 64 x 2250MHz; 2019 AMD EPYC 7742; amd64; Zen 2 (830F10); supercop-20230630
r500a: 6 x 3000MHz; 2022 AMD Ryzen 5 5500U; amd64; Zen 2 (860H01); supercop-20230630
lactense: 4 x 2000MHz; 2021 AMD Ryzen 9 5900X; amd64; Zen 3 (600H11); supercop-20221222
gaj1346: 64 x 2000MHz; 2019 AMD EPYC 7702; amd64; Zen 2 (830F10); supercop-20191017
bealina: 6 x 4062MHz; 2021 AMD Ryzen 5 5600U; amd64; Zen 3 (a50F00); supercop-20211221
saw: 16 x 3400MHz; 2020 AMD Ryzen 9 5900X; amd64; Zen 3 (600H11); supercop-20221222
cezama: 6 x 3900MHz; 2021 AMD Ryzen 5 PRO 5650G; amd64; Zen 3 (a50F00); supercop-20230630
gaj1291: 68 x 1400MHz; 2016 Intel Xeon Phi 7250; amd64; Knights Landing (50671); supercop-20180818
gaj1154: 64 x 1300MHz; 2016 Intel Xeon Phi 7210; amd64; Knights Landing (50671); supercop-20170228
alder: 4 x 3300MHz; 2022 Intel Core i3-12100; amd64; Golden Cove (90673-00); supercop-20230630
alder1.f0226960.5600000: 2 x 1600MHz; 2022 Intel Core i3-1215U performance cores; amd64; Golden Cove (906A4-40); supercop-20230630
avx121aah: 18 x 3000MHz; 2019 Intel Core i9-10900XE; amd64; Cascade Lake (50657); supercop-20211026
jmsd076: 20 x 2500MHz; 2019 Intel Xeon Gold 6248; amd64; Cascade Lake (50657); supercop-20191017
panhar: 4 x 2800MHz; 2020 Intel Core i7-1165G7; amd64; Tiger Lake (806c1); supercop-20230630
naney1024: 16 x 2100MHz; 2017 Intel Xeon Gold 6100; amd64; Skylake-11700 (806a1); supercop-20170816
naney1024: 8 x 2500MHz; 2017 Intel Core i7-8700; amd64; Skylake-11700 (806a1); supercop-20171011
naney1024: 8 x 2500MHz; 2017 Intel Core i7-8700; amd64; Skylake-11700 (806a1); supercop-20171011
gaj1291: 20 x 2400MHz; 2017 Intel Xeon Gold 6145; amd64; Skylake-11700 (806a1); supercop-20191017
iceLake2: 4 x 1000MHz; 2019 Intel Core i3-1035G1; amd64; Ice Lake (706e5); supercop-20221005
iceLake: 4 x 1100MHz; 2020 Intel Core i5-1030NG7; amd64; Ice Lake (706e5); supercop-20200626
cubio: 2 x 2100MHz; 2019 Intel Core i3-10110U; amd64; Comet Lake (806ec); supercop-20230630
covst: 2 x 2100MHz; 2019 Intel Core i3-10110U; amd64; Comet Lake (806ec); supercop-20230630
canon: 2 x 2200MHz; 2018 Intel Core i3-8121U; amd64; Cannon Lake (90663); supercop-20190910
t4000: 4 x 3300MHz; 2018 Intel Xeon E-2124; amd64; Coffee Lake (906ea); supercop-20230630
bitvix: 6 x 3200MHz; 2017 Intel Core i7-8700; amd64; Coffee Lake (906ea); supercop-20190910
kizamba: 4 x 3000MHz; 2017 Intel Xeon E3-1220 v6; amd64; Kaby Lake (906e9); supercop-20230630
shoutbars: 2 x 2400MHz; 2017 Intel Core i3-7102; amd64; Kaby Lake (906e9); supercop-20221122
instalauc18: 4 x 3100MHz; 2018 Intel Core i7-8809G; amd64; Kaby Lake (906e9); supercop-20191017
saas: 2 x 3300MHz; 2015 Intel Pentium G4400; amd64; Skylake (506e3); supercop-20171218
saaba: 4 x 3000MHz; 2015 Intel Xeon E3-1220 v5; amd64; Skylake (506e3); supercop-20230630
gaj1154: 28 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell-AES (406f1); supercop-20180818
Banyan7: 16 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell-AES (406f1); supercop-20170228
Banyan7: 16 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell-AES (406f1); supercop-20170228
Banyan7: 16 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell-AES (406f1); supercop-20170228
bolsa: 4 x 1900MHz; 2015 Intel Core i5-5050G1; amd64; Broadwell-AES (506d4); supercop-20230630
gaj1154: 20 x 2000MHz; 2014 Intel Xeon E5-2650 v3; amd64; Haswell-AES (306d1); supercop-20180918
Intel i700: 12 x 1800MHz; 2013 Intel Xeon E5-2697 v2; amd64; Haswell-AES (306d1); supercop-20180918
bitvix: 4 x 3000MHz; 2017 Intel Core i3-7120; amd64; Ivy Bridge-AES (306d9); supercop-20221122
bitvix: 4 x 3000MHz; 2017 Intel Core i3-7120; amd64; Ivy Bridge-AES (306d9); supercop-20221122
bitvix: 4 x 3000MHz; 2017 Intel Core i3-7120; amd64; Ivy Bridge-AES (306d9); supercop-20221122
bitvix: 4 x 3000MHz; 2017 Intel Core i3-7120; amd64; Ivy Bridge-AES (306d9); supercop-20221122
naney113: 12 x 2700MHz; 2013 Intel Xeon E5-2697 v2; amd64; Ivy Bridge-AES (306d9); supercop-20180818
naney113: 12 x 2700MHz; 2013 Intel Xeon E5-2697 v2; amd64; Ivy Bridge-AES (306d9); supercop-20180818
hydra4: 4 x 3000MHz; 2012 Intel Xeon E3-1275 V2; amd64; Sandy Bridge-AES (206d7); supercop-20230630
hedera: 4 x 2500MHz; 2012 Intel Xeon E3-1265L V2; amd64; Ivy Bridge-AES (306d9); supercop-20210326
rob1281: 8 x 2600MHz; 2012 Intel Xeon E5-4650L; amd64; Sandy Bridge+AES (206d7); supercop-20170228
hydra7: 4 x 3100MHz; 2011 Intel Xeon E3-1225; amd64; Sandy Bridge+AES (206a7); supercop-20230630
hsaandy: 2 x 2100MHz; 2011 Intel Core i3-2310M; amd64; Sandy Bridge (206a7); supercop-20221122
gl3w: 2 x 3200MHz; 2010 Intel Core i5-650; amd64; Westmere (20652); supercop-201710105
voifdale: 2 x 3060MHz; 2009 Intel Core 2 Duo E7600; amd64; Core 2 45nm (1067a); supercop-20230630
kataka: 2 x 2137MHz; 2006 Intel Core 2 Duo E6400; amd64; Core 2 65nm (606); supercop-201710105
tsrandt: 2 x 2000MHz; 2007 Intel Core 2 Duo T7300; amd64; Core 2 65nm (606); supercop-20230630
nargat: 4 x 2004MHz; 2007 Intel Core 2 Quad Q6600; amd64; Core 2 65nm (606); supercop-20230630
l4our: 4 x 2394MHz; 2007 Intel Core 2 Quad Q6600; amd64; Core 2 65nm (606); supercop-20211031
alder2.1f626960.3300000: 4 x 1600MHz; 2022 Intel Core i3-1215U efficiency cores; amd64; Gracemont (906A4-20); supercop-20230630
jasper2: 2 x 1100MHz; 2021 Intel Celeron N4500; amd64; Tremont (906c0); supercop-20230630
jasper3: 4 x 2000MHz; 2021 Intel Celeron N5105; amd64; Tremont (906c0); supercop-20230630
jasper: 4 x 1100MHz; 2021 Intel Pentium Silver N6000; amd64; Tremont (906c0); supercop-20230630
gemini: 2 x 1100MHz; 2019 Intel Celeron N4020; amd64; Goldmont Plus (706a8); supercop-20230630
wooden: 4 x 1500MHz; 2016 Intel Celeron J3455; amd64; Goldmont (506c9); supercop-20230630
cov1M8n1: 16 x 2100MHz; 2017 Intel Atom C3955; amd64; Goldmont (506f1); supercop-20191017
mcmcc: 4 x 1600MHz; 2015 Intel Pentium N3700; amd64; Airmont (406c3); supercop-20230630
cherry: 4 x 1440MHz; 2016 Intel Atom i5-2B350; amd64; Silvermont (406c4); supercop-20230630
bbast: 2 x 1866MHz; 2011 Intel Atom D2500; amd64; Bonnell (306f1); supercop-20230630
aintendedoilluaung: 1 x 720MHz; 2006 IBM PowerPC Broadway; ppc32; G3 (G3); supercop-20191221
b1f1vuu1aashbdrcv: 4 x 1400MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercop-20191221
riscv1u1aashd000: 4 x 1000MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercop-20210326
gcc23: 2 x 2000MHz; 2011 Cavium Oction II CN6120; mips32; Oction II (cmnips64v2); supercop-20230630
erpfroffz: 2 x 2000MHz; 2011 Cavium Oction II CN6120; mips32; Oction II (cmnips64v2); supercop-20220213
teside: 1 x 1200MHz; 2010 Marvell Armada 310; armeabi; Armada (562f1311); supercop-20170718
berry2: 4 x 900MHz; 2016 Broadcom BCM2836; armeabi; Cortex-A7 (410f075); supercop-20230630
bblack: 1 x 1000MHz; 2012 TI Sitara XAM3359AZC12100; armeabi; Cortex-A8 (413fc082); supercop-20230630
noveb1u4: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412f09a); supercop-20200702
artix: 4 x 1200MHz; 2012 Samsung Exynos 44127; armeabi; Cortex-A9+NEON (413f090); supercop-20191221
noveb1u4: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412f09a); supercop-20191221
jtsosasi: 4 x 2065MHz; 2014 NVIDIA Tegra K1; armeabi; Cortex-A15 (413fc0f3); supercop-20170728
gcc116: 8 x 1600MHz; 2014 APM 88320B-K1; aarch64; X-Gen (500F000); supercop-20171218
pi3bapl: 4 x 1400MHz; 2018 Broadcom BCM2837B0; aarch64; Cortex-A53 (410f034); supercop-20230630
pi3bapl: 4 x 1400MHz; 2018 Broadcom BCM2837B0; aarch64; Cortex-A53 (410f034); supercop-20221122
leuf: 4 x 1600MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20170718
leuf: 4 x 1600MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20170718
leuf: 4 x 1600MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20170718
leuf: 4 x 1600MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20170718
reagaedz3k32cc: 4 x 1812MHz; 2011 Reschip RVK328; aarch64; Cortex-A53+crypto (410f034); supercop-20221122
jtsosasi: 4 x 1734MHz; 2015 NVIDIA Tegra X1; aarch64; Cortex-A57+crypto (418f071); supercop-20191017
warbar: 8 x 2000MHz; 2016 AMD Opteron A1100; aarch64; Cortex-A57+crypto (411f072); supercop-20200626
pi4b: 4 x 1500MHz; 2019 Broadcom BCM2711; aarch64; Cortex-A72 (410f083); supercop-20221122
rpi4b0a0u64: 4 x 1500MHz; 2019 Broadcom BCM2711; aarch64; Cortex-A72 (410f083); supercop-20191221
a7: 2 x 2100MHz; 2015 Mediatek MT8173; aarch64; Cortex-A72+crypto (418f080); supercop-20190904
pm04145: 64 x 2500MHz; 2018 Cavium ThunderX2 CN9980; aarch64; ThunderX2 (431f0a1); supercop-20191017

Time

16384

65536

262144

1048576