

crypto_core
wforcesntrup1277
implementations

amd64 Bobcat

amd64 K8

amd64 K10 65nm

amd64 K10 45nm

amd64 K10 32nm

amd64 Bulldozer

amd64 Piledriver

amd64 Zen

amd64 Zen 2

amd64 Zen 3

amd64 Knights Landing

amd64 Golden Cove

amd64 Cascade Lake

amd64 Tiger Lake

amd64 Skylake+512x2

amd64 Ice Lake

amd64 Comet Lake

amd64 Cannon Lake

amd64 Coffee Lake

amd64 Kaby Lake

amd64 Skylake

amd64 Broadwell+AES

amd64 Haswell+AES

amd64 Ivy Bridge+AES

amd64 Sandy Bridge+AES

amd64 Sandy Bridge

amd64 Westmere

amd64 Core 2 45nm

amd64 Core 2 65nm

amd64 Gracemont

amd64 Tremont

amd64 Goldmont Plus

amd64 Goldmont

amd64 Airmont

amd64 Silvermont

amd64 Bonnell

ppc32 G3

riscv64 U54

mips32 Oocteon II

armeabi Armada

armeabi Cortex-A7

armeabi Cortex-A8

armeabi Cortex-A9+NEON

armeabi Cortex-A15

aarch64 X-Gene

aarch64 Cortex-A53

aarch64 Cortex-A53+crypto

aarch64 Cortex-A57+crypto

aarch64 Cortex-A72

aarch64 Cortex-A72+crypto

aarch64 ThunderX2


Time

128

512

2048

8192



https://bench.cr.yp.to
20230702

bbobcat: 2 x 1650MHz; 2011 AMD G-T56N; amd64; Bobcat (500F10); supercop-20230630
m4e50: 2 x 1650MHz; 2011 AMD E-450; amd64; Bobcat (500F20); supercop-20230618
nae: 2 x 2000MHz; 2006 AMD Athlon 64 X2; amd64; K8 (40f82); supercop-201710105
gcc16: 8 x 2194MHz; 2008 AMD Opteron 8354; amd64; K10 65nm (100f23); supercop-20171218
hydra3: 6 x 3300MHz; 2010 AMD Phenom II X6 1100T; amd64; K10 45nm (100f0a); supercop-20171218
sonnigstar: 4 x 3200MHz; 2009 AMD Phenom II X4 955; amd64; K10 45nm (100f42); supercop-20170904
h3ae: 1 x 1700MHz; 2010 AMD Athlon II Neo K125; amd64; K10 45nm (100f63); supercop-201710105
hydra4: 4 x 2600MHz; 2011 AMD A8-3850; amd64; K10 32nm (300f10); supercop-20230630
hydra5: 4 x 2900MHz; 2011 AMD A8-3850; amd64; K10 32nm (300f10); supercop-20230630
bobcat: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600F20); supercop-20171218
calista: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600F20); supercop-20171218
hydra6: 4 x 3100MHz; 2011 AMD FX-8120; amd64; Bulldozer (600F12); supercop-20171218
shaver210: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600F20); supercop-20230630
hydra9: 2 x 3800MHz; 2012 AMD A10-5800K; amd64; Piledriver (610F01); supercop-20171218
fpatrioty: 2 x 2000MHz; 2012 AMD A10-4655M; amd64; Piledriver (610F01); supercop-20200618
zhang: 8 x 3000MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
zhang: 8 x 3000MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800H11); supercop-20170855
zhang: 4 x 3100MHz; 2017 AMD Ryzen 3 1300; amd64; Zen (800H11); supercop-20170855
zhang: 4 x 3100MHz; 2017 AMD Ryzen 3 1300; amd64; Zen (800H11); supercop-20170855
dali: 2 x 2000MHz; 2012 AMD A10-5600; amd64; Piledriver (610F01); supercop-201710105
zeno: 64 x 2250MHz; 2019 AMD EPYC 7742; amd64; Zen 2 (830F10); supercop-20230630
zeno2: 6 x 3000MHz; 2022 AMD Ryzen 5 4500U; amd64; Zen 2 (860H01); supercop-20230630
lactance: 4 x 2600MHz; 2020 AMD Ryzen 3 3300U; amd64; Zen 2 (830F10); supercop-20230630
gwj1346: 64 x 2000MHz; 2019 AMD EPYC 7702; amd64; Zen 2 (830F10); supercop-20191017
beeline: 6 x 4062MHz; 2021 AMD Ryzen 5 5560U; amd64; Zen 3 (a50F00); supercop-20211122
san: 16 x 3400MHz; 2020 AMD Ryzen 9 5950X; amd64; Zen 3 (a20F10); supercop-20230630
cezanne: 6 x 3900MHz; 2021 AMD Ryzen 5 PRO 5650G; amd64; Zen 3 (a50F00); supercop-20230630
gwj1291: 68 x 1400MHz; 2016 Intel Xeon Phi 7210; amd64; Knights Landing (50671); supercop-20180818
gwj1154: 64 x 1300MHz; 2016 Intel Xeon Phi 7210; amd64; Knights Landing (50671); supercop-20170228
alder: 4 x 3300MHz; 2022 Intel Core i3-12100; amd64; Golden Cove (90673-00); supercop-20230630
alder2.1f62690.5600000: 2 x 1600MHz; 2022 Intel Core i3-1215U performance cores; amd64; Golden Cove (906A4-40); supercop-20230630
avx512math: 18 x 3000MHz; 2019 Intel Core i9-10980X; amd64; Cascade Lake (50657); supercop-20201126
peno476: 20 x 2500MHz; 2019 Intel Xeon Gold 6248; amd64; Cascade Lake (50657); supercop-20191017
panther: 4 x 2800MHz; 2020 Intel Core i7-1165G7; amd64; Tiger Lake (806c1); supercop-20230630
sanj1024: 16 x 2100MHz; 2017 Intel Xeon Gold 6150; amd64; Skylake+512x2 (906A1); supercop-20170804
sanj2048: 8 x 2000MHz; 2017 Intel Core i7-7700; amd64; Skylake+512x2 (906A1); supercop-20171121
sanj4096: 4 x 1900MHz; 2017 Intel Core i7-7700; amd64; Skylake+512x2 (906A1); supercop-20171121
sanj8192: 2 x 1800MHz; 2017 Intel Core i7-7700; amd64; Skylake+512x2 (906A1); supercop-20171121
icelake2: 4 x 1000MHz; 2019 Intel Core i3-1035G1; amd64; Ice Lake (706e5); supercop-20221005
icelake: 4 x 1100MHz; 2020 Intel Core i5-1030NG7; amd64; Ice Lake (706e5); supercop-20200626
cusio: 2 x 2100MHz; 2019 Intel Core i3-10110U; amd64; Comet Lake (806ec); supercop-20230630
cosw: 2 x 2100MHz; 2019 Intel Core i3-10110U; amd64; Comet Lake (806ec); supercop-20230630
cannon: 2 x 2200MHz; 2018 Intel Core i3-8121U; amd64; Cannon Lake (90663); supercop-20190910
r3000: 4 x 3300MHz; 2018 Intel Xeon E-2124; amd64; Coffee Lake (906a3); supercop-20230630
ntv316: 6 x 3200MHz; 2017 Intel Core i7-8700; amd64; Coffee Lake (906a3); supercop-20190910
kabyana: 4 x 3000MHz; 2017 Intel Xeon E3-1220 v6; amd64; Kaby Lake (906e9); supercop-20230630
shoahara: 2 x 2400MHz; 2017 Intel Core i3-7100; amd64; Kaby Lake (906e9); supercop-20211122
intelauc18: 4 x 3100MHz; 2018 Intel Core i7-8089G; amd64; Kaby Lake (906e9); supercop-20191017
san: 2 x 3300MHz; 2015 Intel Pentium G4400; amd64; Skylake (506c3); supercop-20171218
san: 4 x 3000MHz; 2015 Intel Xeon E3-1220 v5; amd64; Skylake (506c3); supercop-20230630
gwj1461: 28 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell+AES (406f1); supercop-20180818
sanj1772: 16 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell+AES (406f1); supercop-20170228
sanj1772: 16 x 2400MHz; 2016 Intel Xeon E5-2650 v4; amd64; Broadwell+AES (406f1); supercop-20170228
bolton: 8 x 1700MHz; 2015 Intel Core i3-5005A1; amd64; Broadwell+AES (506d4); supercop-20230630
san: 2 x 1900MHz; 2015 Intel Core i3-5005A1; amd64; Broadwell+AES (506d4); supercop-20230630
gwj1465: 20 x 2000MHz; 2014 Intel Xeon E5-2650 v3; amd64; Haswell+AES (306e1); supercop-20190910
intelsoc: 12 x 2000MHz; 2013 Intel Xeon E3-1275 V2; amd64; Ivy Bridge+AES (306a9); supercop-20230630
intelsoc: 4 x 2000MHz; 2013 Intel Xeon E3-1275 V2; amd64; Ivy Bridge+AES (306a9); supercop-20230630
sanj1610: 4 x 2000MHz; 2012 Intel Xeon E5-2650 v2; amd64; Haswell+AES (306e1); supercop-20230630
sanj1610: 4 x 2000MHz; 2012 Intel Xeon E5-2650 v2; amd64; Haswell+AES (306e1); supercop-20230630
sanj513: 12 x 2700MHz; 2013 Intel Xeon E5-2697 v2; amd64; Ivy Bridge+AES (306a9); supercop-20180818
sanj513: 12 x 2700MHz; 2013 Intel Xeon E5-2697 v2; amd64; Ivy Bridge+AES (306a9); supercop-20180818
hydra6: 4 x 3500MHz; 2012 Intel Xeon E3-1275 V2; amd64; Ivy Bridge+AES (306a9); supercop-20230630
hedera: 4 x 2500MHz; 2012 Intel Xeon E3-1265L V2; amd64; Ivy Bridge+AES (306a9); supercop-20210326
robia281: 8 x 2600MHz; 2012 Intel Xeon E5-4650L; amd64; Sandy Bridge+AES (206d7); supercop-20170228
hydra7: 4 x 3100MHz; 2011 Intel Xeon E3-1225; amd64; Sandy Bridge+AES (206a7); supercop-20230630
h6sandy: 2 x 2100MHz; 2011 Intel Core i3-2310M; amd64; Sandy Bridge (206a7); supercop-20211122
g1ysw: 2 x 3200MHz; 2010 Intel Core i5-650; amd64; Westmere (20652); supercop-201710105
voirdale: 2 x 3060MHz; 2009 Intel Core 2 Duo E7600; amd64; Core 2 45nm (1067a); supercop-20230630
katana: 2 x 2137MHz; 2006 Intel Core 2 Duo E6400; amd64; Core 2 65nm (66f); supercop-201710105
tsrdant: 2 x 2000MHz; 2007 Intel Core 2 Duo T7300; amd64; Core 2 65nm (66f); supercop-20230630
nanquai: 4 x 2304MHz; 2007 Intel Core 2 Quad Q6600; amd64; Core 2 65nm (66f); supercop-20230630
lalour: 4 x 2394MHz; 2007 Intel Core 2 Quad Q6600; amd64; Core 2 65nm (66f); supercop-20201130
alder2.1f62690.3300000: 4 x 1600MHz; 2022 Intel Core i3-1215U efficiency cores; amd64; Gracemont (906A4-20); supercop-20230630
jasper2: 2 x 1100MHz; 2021 Intel Celeron N4500; amd64; Tremont (906c0); supercop-20230630
jasper3: 4 x 2000MHz; 2021 Intel Celeron N5105; amd64; Tremont (906c0); supercop-20230630
jasper: 4 x 1100MHz; 2021 Intel Pentium Silver N6000; amd64; Tremont (906c0); supercop-20230630
gemini: 2 x 1100MHz; 2019 Intel Celeron N4020; amd64; Goldmont Plus (706a8); supercop-20230630
wooden: 4 x 1500MHz; 2016 Intel Celeron J3455; amd64; Goldmont (506c9); supercop-20230630
soviM8h1: 16 x 2100MHz; 2017 Intel Atom C3955; amd64; Goldmont (506f1); supercop-20191017
mccmc: 4 x 1600MHz; 2015 Intel Pentium N3700; amd64; Airmont (406c3); supercop-20230630
cherry: 4 x 1440MHz; 2016 Intel Atom i5-28350; amd64; Silvermont (406c4); supercop-20230630
bbaton: 2 x 1866MHz; 2011 Intel Atom D2500; amd64; Bonnell (306f1); supercop-20230630
alntendosilluaxng: 1 x 720MHz; 2006 IBM PowerPC Broadway; ppc32; G3 (G3); supercop-20191221
hifiveu54aahedrvic: 4 x 1400MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercop-20191221
riscvua54aahed000: 4 x 1000MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercop-20210326
gcc23: 2 x 2000MHz; 2011 Cavium Octeon II CN6120; mips32; Octeon II (cmnips64v2); supercop-20230630
hffz7: 2 x 2000MHz; 2011 Cavium Octeon II CN6120; mips32; Octeon II (cmnips64v2); supercop-20220213
tesla: 1 x 1200MHz; 2010 Marvell Armada 310; armeabi; Armada (562f311); supercop-20170718
berry2: 4 x 900MHz; 2016 Broadcom BCM2836; armeabi; Cortex-A7 (410f075); supercop-20230630
black: 1 x 1000MHz; 2012 TI Sitara XAM3359AZC12100; armeabi; Cortex-A8 (413fc082); supercop-20230630
november4: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412fc09a); supercop-20200702
artix: 4 x 1200MHz; 2012 Samsung Exynos 44127; armeabi; Cortex-A9+NEON (413fc090); supercop-20191221
november4s: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412fc09a); supercop-20191221
jetsonati: 4 x 2065MHz; 2014 NVIDIA Tegra K1; armeabi; Cortex-A15 (413fc0f3); supercop-20170725
gcc16: 8 x 1600MHz; 2014 APM 88320B-X1; aarch64; X-Gene (500F000); supercop-20171218
pi3aplus: 4 x 1400MHz; 2018 Broadcom BCM2837B0; aarch64; Cortex-A53 (410f034); supercop-20230630
pi3plus: 4 x 1400MHz; 2018 Broadcom BCM2837B0; aarch64; Cortex-A53 (410f034); supercop-20211122
leeds: 4 x 1500MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20170704
tepotonathidoc: 4 x 1500MHz; 2015 ARMv8-A Cortex-A53; aarch64; Cortex-A53+crypto (410f034); supercop-20191221
gogolacraslav: 4 x 1500MHz; 2015 NXP i.MX 8M; aarch64; Cortex-A53+crypto (410f034); supercop-20191221
reegadesk3030c: 4 x 1812MHz; 2015 Rockchip RK3288; aarch64; Cortex-A53+crypto (410f034); supercop-20191221
jetsonati: 4 x 1734MHz; 2015 NVIDIA Tegra X1; aarch64; Cortex-A57+crypto (418f071); supercop-20191017
warbar: 8 x 2000MHz; 2016 AMD Opteron A1100; aarch64; Cortex-A57+crypto (411f072); supercop-20200626
pi4b: 4 x 1500MHz; 2019 Broadcom BCM2711; aarch64; Cortex-A72 (410f083); supercop-20211122
rp16bun64: 4 x 1500MHz; 2019 Broadcom BCM2711; aarch64; Cortex-A72 (410f083); supercop-20191221
a7: 2 x 2100MHz; 2015 Mediatek MT8173; aarch64; Cortex-A72+crypto (418f080); supercop-20190904
pmo4145: 64 x 2500MHz; 2018 Cavium ThunderX2 CN9980; aarch64; ThunderX2 (431f0a1); supercop-20191017