


- amd64 Zen2
- amd64 Zen
- amd64 KnLanding
- amd64 CascadeLake
- amd64 SL+512x2
- amd64 IceLake
- amd64 CometLake
- amd64 CannonLake
- amd64 CoffeeLake
- amd64 KabyLake
- amd64 Skylake
- amd64 BW+AES
- amd64 HW+AES
- amd64 IB+AES
- amd64 SB+AES
- amd64 Sandy Bridge
- amd64 Piledriver
- amd64 Bulldozer
- amd64 Westmere
- amd64 C2 65nm
- amd64 K10 32nm
- amd64 K10 45nm
- amd64 K10 65nm
- amd64 Goldmont
- amd64 K8
- amd64 Bobcat
- amd64 Atom
- ppc32 G3
- riscv64 U54
- mips32 Oction II
- armeabi Armada
- armeabi Cortex-A7
- armeabi Cortex-A9+NEON
- armeabi Cortex-A15
- aarch64 X-Gen
- aarch64 A53
- aarch64 A53+crypto
- aarch64 A57+crypto
- aarch64 A72
- aarch64 A72+crypto
- aarch64 ThunderX2



gej1346: 64 x 2000MHz; 2019 AMD EPYC 7702; amd64; Zen2 (830f10); supercep-20191017
ryzen: 8 x 2994MHz; 2017 AMD EPYC 7 1700; amd64; Zen (800f11); supercep-20170904
ryzen: 8 x 3000MHz; 2017 AMD Ryzen 7 1700; amd64; Zen (800f11); supercep-20210604
ryzen: 6 x 3200MHz; 2017 AMD Ryzen 5 1600; amd64; Zen (800f11); supercep-20210604
ryzen: 4 x 3100MHz; 2017 AMD Ryzen 3 1200; amd64; Zen (800f11); supercep-20200906
gej1291: 64 x 1400MHz; 2016 Intel Xeon Phi 7250; amd64; KnLanding (50671); supercep-20180818
gej1154: 64 x 1300MHz; 2016 Intel Xeon Phi 7210; amd64; KnLanding (50671); supercep-20170228
av513naah: 18 x 3000MHz; 2019 Intel Core i9-10980XE; amd64; CascadeLake (50657); supercep-20210126
mead076: 20 x 2500MHz; 2019 Intel Xeon Gold 6248; amd64; CascadeLake (50657); supercep-20191017
naany1024: 18 x 2700MHz; 2017 Intel Xeon Gold 6150; amd64; SL+512x2 (50654); supercep-20170904
sl: 6 x 3000MHz; 2017 Intel Core i7-7800X; amd64; SL+512x2 (50654); supercep-20181123
naany023: 20 x 2400MHz; 2017 Intel Xeon Gold 6148; amd64; SL+512x2 (50654); supercep-20191017
naany148: 40 x 2000MHz; 2017 Intel Xeon Gold 6148; amd64; SL+512x2 (50654); supercep-20191017
gej1239: 32 x 2100MHz; 2017 Intel Xeon Gold 6130; amd64; SL+512x2 (50654); supercep-20191017
icelake: 4 x 1100MHz; 2020 Intel Core i5-1030NG7; amd64; icelake (706e5); supercep-20200826
comet: 2 x 2100MHz; 2019 Intel Core i3-10110U; amd64; CometLake (806ec); supercep-20210604
cannon: 2 x 2200MHz; 2018 Intel Core i3-8121U; amd64; CannonLake (60663); supercep-20191010
r2400: 4 x 3300MHz; 2018 Intel Xeon E-2124; amd64; CoffeeLake (906ea); supercep-20210604
bitvise: 6 x 3200MHz; 2017 Intel Core i7-8700; amd64; CoffeeLake (906ea); supercep-20191010
kizomba: 4 x 3000MHz; 2017 Intel Xeon E3-1220 v6; amd64; KabyLake (906e9); supercep-20210604
istalacsi1: 4 x 3100MHz; 2018 Intel Core i7-8090G; amd64; KabyLake (906e9); supercep-20191017
istalacsi7: 2 x 3500MHz; 2017 Intel Core i7-7567U; amd64; KabyLake (906e9); supercep-20191017
saab: 4 x 3000MHz; 2015 Intel Pentium G4400; amd64; Skylake (506e3); supercep-20171218
saab: 4 x 3000MHz; 2015 Intel Xeon E3-1220 v5; amd64; Skylake (506e3); supercep-20210604
gej1441: 28 x 2400MHz; 2016 Intel Xeon E5-2680 v4; amd64; BW+AES (406f1); supercep-20180818
naany387: 14 x 2400MHz; 2016 Intel Xeon E5-2680 v4; amd64; BW+AES (406f1); supercep-20170228
gej1122: 28 x 2400MHz; 2016 Intel Xeon E5-2680 v4; amd64; BW+AES (406f1); supercep-20171020
bakers: 8 x 1700MHz; 2016 Intel Xeon E5-2609 v4; amd64; BW+AES (406f1); supercep-20210604
gej1160: 20 x 2300MHz; 2014 Intel Xeon E5-2650 v3; amd64; HW+AES (306f2); supercep-20180818
gej1202: 24 x 2500MHz; 2014 Intel Xeon E5-2680 v3; amd64; HW+AES (306f2); supercep-20171020
rhlacsa: 12 x 2500MHz; 2014 Intel Xeon E5-2650 v3; amd64; HW+AES (306f2); supercep-20170228
lipap: 4 x 3100MHz; 2013 Intel Xeon E3-1220 v3; amd64; HW+AES (306c3); supercep-20210604
l1acsa: 4 x 3000MHz; 2013 Intel Xeon E3-1275 v3; amd64; HW+AES (306c3); supercep-20210604
naany13: 12 x 2700MHz; 2013 Intel Xeon E5-2697 v2; amd64; IB+AES (306e4); supercep-20180818
bakers: 4 x 2500MHz; 2012 Intel Xeon E3-1265L V2; amd64; IB+AES (306e4); supercep-20210326
hydra8: 4 x 3500MHz; 2012 Intel Xeon E3-1275 V2; amd64; IB+AES (306e4); supercep-20210604
robta281: 8 x 2600MHz; 2012 Intel Xeon E5-4650L; amd64; SB+AES (206e7); supercep-20170228
hfsandy: 2 x 2100MHz; 2011 Intel Core i3-2310M; amd64; Sandy Bridge (206a7); supercep-20200618
hydra9: 2 x 3800MHz; 2012 AMD A10-5800K; amd64; Piledriver (610f01); supercep-20171218
h3trinity: 2 x 2000MHz; 2012 AMD A10-6650M; amd64; Piledriver (610f01); supercep-20200618
bobbae: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600f20); supercep-20171218
calvin: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600f20); supercep-20171218
hydra6: 4 x 3100MHz; 2011 AMD FX-8120; amd64; Bulldozer (600f12); supercep-20171218
saaber214: 4 x 4000MHz; 2012 AMD FX-8350; amd64; Bulldozer (600f20); supercep-20210423
glywa: 2 x 3300MHz; 2010 Intel Core i5-650; amd64; Westmere (20652); supercep-20171016
kataaa: 2 x 2137MHz; 2006 Intel Core 2 Duo E6400; amd64; C2 65nm (6f6); supercep-20171016
naargax: 4 x 2404MHz; 2007 Intel Core 2 Quad Q6600; amd64; C2 65nm (6f6); supercep-20210604
latour: 4 x 2394MHz; 2007 Intel Core 2 Quad Q6600; amd64; C2 65nm (6f6); supercep-20201130
hydra5: 4 x 2900MHz; 2011 AMD A8-3850; amd64; K10 32nm (300f10); supercep-20191221
hydra3: 6 x 3300MHz; 2010 AMD Phenom II X6 1100T; amd64; K10 45nm (100fa0); supercep-20171218
sonniagat8: 4 x 3200MHz; 2009 AMD Phenom II X4 955; amd64; K10 45nm (100fa2); supercep-20170904
hbaee: 1 x 1700MHz; 2010 AMD Athlon II Neo K125; amd64; K10 45nm (100f63); supercep-20171016
gcc16: 8 x 2194MHz; 2008 AMD Opteron 8354; amd64; K10 65nm (100f23); supercep-20171218
sovi163hl: 16 x 2100MHz; 2017 Intel Atom C3955; amd64; Goldmont (506f1); supercep-20191017
nacc: 2 x 2000MHz; 2006 AMD Athlon 64 X2; amd64; K8 (40fb2); supercep-20171016
hbobcat: 2 x 1650MHz; 2011 AMD G-T56N; amd64; Bobcat (500f10); supercep-20171218
h4450: 2 x 1650MHz; 2011 AMD E-450; amd64; Bobcat (500f20); supercep-20200618
hlatoo: 2 x 1866MHz; 2011 Intel Atom D2500; amd64; Atom (30661); supercep-20200618
sinteeovilliauzag: 1 x 729MHz; 2006 IBM PowerPC Broadway; ppc32; G3 (G3); supercep-20191221
hifiveveaashedrac: 4 x 1400MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercep-20191221
riscvuaaashed000: 4 x 1000MHz; 2017 SiFive Freedom U540; riscv64; U54 (sifive,u54-mc); supercep-20210326
exproffsr2: 2 x 2000MHz; 2011 Cavium Oction II CN6120; mips32; Oction II (cmnips64v2); supercep-20210604
tonaid: 1 x 1200MHz; 2010 Marvell Armada 310; armeabi; Armada (562f1311); supercep-20170718
berry2: 4 x 900MHz; 2016 Broadcom BCM2836; armeabi; Cortex-A7 (410f075); supercep-20210604
arveaalas: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412f09a); supercep-20200702
artik: 4 x 1200MHz; 2012 Samsung Exynos 4412; armeabi; Cortex-A9+NEON (413f090); supercep-20191221
arveaalas6: 4 x 1200MHz; 2011 Freescale i.MX6 Quad; armeabi; Cortex-A9+NEON (412f09a); supercep-20191221
jetsont1: 4 x 2065MHz; 2014 NVIDIA Tegra K1; armeabi; Cortex-A15 (413f0f3); supercep-20170725
gcc16: 8 x 1600MHz; 2014 APM 88320B-X1; aarch64; X-Gen (500f000); supercep-20171218
pi3plu: 4 x 1400MHz; 2018 Broadcom BCM2837B0; aarch64; A53 (410f034); supercep-20210604
par3: 4 x 2000MHz; 2015 Amlogic S905; aarch64; A53+crypto (410f034); supercep-20170718
1epotatooa98acc: 4 x 1512MHz; 2016 Amlogic S905X; aarch64; A53+crypto (410f034); supercep-20191221
gnegiacaaalav: 4 x 1500MHz; 2018 Rockchip RK3328; aarch64; A53+crypto (410f034); supercep-20191221
renegaderocr328cc: 4 x 1512MHz; 2017 Rockchip RK3328; aarch64; A53+crypto (410f034); supercep-20191221
jetsont1: 4 x 1734MHz; 2015 NVIDIA Tegra X1; aarch64; A57+crypto (418f071); supercep-20191017
warbear: 8 x 2000MHz; 2016 AMD Opteron A1100; aarch64; A72+crypto (411f072); supercep-20200826
rpi4abutu64: 4 x 1500MHz; 2019 Broadcom BCM2711; aarch64; A72 (410f083); supercep-20191221
ar2: 2 x 2100MHz; 2015 Mediatek MT8173; aarch64; A72+crypto (418f080); supercep-20170904
pmo416: 64 x 2500MHz; 2018 Cavium ThunderX2 CN9980; aarch64; ThunderX2 (431fa13); supercep-20191017